


PursoCal News-Letter


DataBase-3344 V12




• P50L EI30/EI60, with options inside fire, outside or inside and outside:




• P80 glass walls for Finnish customers.



LK78X security pins updated



LK78X – wall fixation, material description added for plates:



- Terrace midrail brush gasket changed from HT1 to JTHT5.
- Added adjufix machining for P94.
- Updated descriptions for Hardwares and accessories that is not supplied by Purso.
- Terrace system updated screw: Z4832 to RUUVI4832.
- P76E fixed drainage Machining on Profiles 23330/23331.
- LK90X added K2573 fastening piece for hinges JSMHAHN/LV20.
- Fixed weight information for articles PUR20xXX.
- P76E changed screw from RUUVI4880 to UPPRUUVI4880.
- LK78X outward open windows hardware changed from MILU to GILU.
- P50L (new) added missing U-values.

What's Coming

- New system P80 EI30 Sa200.
- P76E New glass thickness 60-61mm, new profiles.
- Automatic doors to façade.
- CE Data updated.
- Product CO2 values.

Contacts:
Edgard Bodnar
R&D Specialist
Edgard.Bodnar@purso.com
+370 608 30 796

Customer and Architect support Buildinginfo@purso.fi +358 334 04 600