



2024-03



PursoCal

News-Letter

DataBase-3150
V12



- New P50S system added:

Input glass should require one of combination from this table, if you have other glass combination that is missing from the table, please contact us by email: Edgard.bodnar@purso.com

Glass Input

The selected glass combination is not valid for this system. Possible glass combination for this system:

Thickness outs...	Gap1	Thickness middle	Gap2	Thickness inside	^ Total thick...
8 mm	16 - 16 mm	6 mm	12 - 12 mm	6 mm	48 mm
6 mm	16 - 16 mm	6 mm	14 - 14 mm	6 mm	48 mm
4 mm	16 - 16 mm	6 mm	16 - 16 mm	6 mm	48 mm
10 mm	16 - 16 mm	6 mm	10 - 10 mm	6 mm	48 mm
12 mm	16 - 16 mm	6 mm	8 - 8 mm	6 mm	48 mm
14 mm	16 - 16 mm	6 mm	6 - 6 mm	6 mm	48 mm
9 mm	16 - 16 mm	6 mm	12 - 12 mm	6 mm	49 mm
8 mm	16 - 16 mm	6 mm	13 - 13 mm	6 mm	49 mm
11 mm	16 - 16 mm	6 mm	10 - 10 mm	6 mm	49 mm
7 mm	16 - 16 mm	6 mm	14 - 14 mm	6 mm	49 mm
13 mm	16 - 16 mm	6 mm	8 - 8 mm	6 mm	49 mm
12 mm	16 - 16 mm	6 mm	10 - 10 mm	6 mm	50 mm
6 mm	16 - 16 mm	6 mm	16 - 16 mm	6 mm	50 mm
10 mm	16 - 16 mm	6 mm	12 - 12 mm	6 mm	50 mm
8 mm	16 - 16 mm	6 mm	14 - 14 mm	6 mm	50 mm
14 mm	16 - 16 mm	6 mm	8 - 8 mm	6 mm	50 mm
13 mm	16 - 16 mm	6 mm	10 - 10 mm	6 mm	51 mm
11 mm	16 - 16 mm	6 mm	12 - 12 mm	6 mm	51 mm
9 mm	16 - 16 mm	6 mm	14 - 14 mm	6 mm	51 mm
7 mm	16 - 16 mm	6 mm	16 - 16 mm	6 mm	51 mm
10 mm	16 - 16 mm	6 mm	13 - 13 mm	6 mm	51 mm
8 mm	16 - 16 mm	6 mm	16 - 16 mm	6 mm	52 mm
14 mm	16 - 16 mm	6 mm	10 - 10 mm	6 mm	52 mm

OK

- LK90X replaced gasket “QL46105” with
New gasket “DX787”, updated U-values.
- Added outside open window LK90eco into P50L curtain wall.
- Fixed “Terrace system” corner connection in Position properties
- LK78X outward open windows- added missing wall connection
- P80 shoot bolt closure machining added.
- P76E new U-values together with PUR-insulator, new transom and mullion, new solutions -Testing version(Special update if needed)

What's Coming

- LK78X security pins update
- P50L EI30-60
- P80 glass wall for Finnish customers
- P76E New glass thickness 60-61mm, new profiles

Contacts:

Edgard Bodnar
R&D Specialist
Edgard.Bodnar@purso.com
+370 608 30 796

Customer and Architect support
Buildinginfo@purso.fi
+358 334 04 600